

Servicii de reparat POMPA WILO 3.6KW/1000T

I.D.: 42384646

Data publicarii	02.04.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.980,00 RON - 1.980,00 RON

Descriere: Servicii de reparat POMPA WILO 3.6KW/1000T, demontat-montat, rebobinat stator, inluit rulmenti SKF, inlocuit etansare pachet, ulei, sudat corp pompa, rectificat ax rotor, diverse
