
reparat POMPA WILO 4.8KW/3000T, WILO 2.5KW/3000T

I.D.: 48688651

Data publicarii	03.08.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.850,00 RON - 3.850,00 RON

Descriere: 1. demontat montat, rebobinat stator, inlocuit rulmenti SKF, inlocuit etansari mecanice, reparat cablu alimentare +ulei siliconic 2. rebobinat stator, inlocuit rulmenti si inlocuit etansare mecanica
