
REPARATIE SURSA DE PUTERE VARIATOR DE INTRARE

I.D.: 100301790

Data publicarii	18.07.24	Coduri CPV	50116100-2
-----------------	----------	------------	------------

Pretul estimativ: 18.320,00 RON - 18.320,00 RON

Descriere: REPARATIE SURSA DE PUTERE VARIATOR DE INTRARE 3 TBZ SKODA 24TR (34198, 34203)-2
BUC REPARATIE SURSA DE PUTERE VARIATOR DE INTRARE 4 TBZ SKODA 24TR (34199)- 1 BUC
REPARATIE SURSA DE PUTERE VARIATOR DE INTRARE 5 TBZ SKODA 24TR (34201)- 1 BUC
Comanda 1496/10.07.2024
