
reparatie statie de vacuum Medaes

I.D.: 73430541

Data publicarii	23.09.22	Coduri CPV	50000000-5 98300000-6
-----------------	----------	------------	-----------------------

Pretul estimativ: 10.830,14 RON - 10.830,14 RON

Descriere: reparatie statie de vacuum Medaes cu inlocuirea urmatoarelor componente: 1 buc - OEM rotor blade - 1.680,59 lei 1 buc - OEM VC oring - 57.54 lei 1 buc - OEM Shaft Sleeve - 177.08 lei 1 buc - OEM Shaft Seal - 423.83 lei 1 buc - OEM Vac Pump Circlip - 58.71 lei 1 buc - OEM Coupling Rotex 28 Driven - 1.592,70 lei 1 buc - OEM Vac Pump Rotex 28 - 956.49 lei 1 buc - Vacuum Pump Service Kit 100 - 5.883,20 lei
