
REPARATII POMPE SUMERSIBILE

I.D.: 65909587

Data publicarii	01.02.22	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 3.692,00 RON - 3.692,00 RON

Descriere: REPARATII POMPA HOMA TP 50 : rebobinat ; inlocuire rulmentii si presutupe . REPARATII POMPA FLAYGT 208007: rebobinat ; lucrari mecanice conexe ; schimbat rulmentii; semering ; presutupe ; ulei REPARATII POMPA WILO CU TOCATOR : rebobinat ; inlocuire rulmenti si presutupe ; lucrari mecanice conexe; REPARATII POMPA WILO FA :rebobinat ; inlocuire rulmenti ; presutupe ; lucrari mecanice conexe ; echilibrare dinamica
