
Reparatie pompa SP17-5 si GRUNDFOS SP5A-25

I.D.: 102380184

Data publicarii	02.09.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 11.900,00 RON - 11.900,00 RON

Descriere: Lucrari de reparatie pompa Grundfos SP17-5, care includ: demontare pompa, constatare si inlocuire urmatoarele piese, kit ax 1buc., kit reparatie 1buc., motor 3 kw 1buc., termocupla 1buc. Lucrari de reparatie pompa Grundfos SP5A-25 care includ: demontare pompa, constatare si inlocuire piese: unitate pompare 1buc., termocupla 1buc., kit motor 1buc.
