

---

## Reparatie sararita Multicar

I.D.: 67545897

---

Data  
publicarii 28.03.22

Coduri CPV 50110000-9

---

Pretul  
estimativ: 3.063,69 RON - 3.063,69 RON

---

Descriere: Conditii refuzate: STECHER+PRIZA ELECTRICA - 2 seturi, PROX SWITCH - Senzor PAM III - 1 buc., Lichid frana - 1 buc., Materiale consumabile - 1 set. Diagnoza electrica suprastructura, Manopera reparatie electrica, D/M inlocuit senzor, Verificare de functionalitate I.

---