

Servicii de reparare masina de spalat ind. Electrolux

I.D.: 76607705

Data publicarii 14.12.22 Coduri CPV 50532000-3

Pretul estimativ: 1.152,00 RON - 1.152,00 RON

Descriere: Reparatie masina de spalat rufe industriala Electrolux 35 kg , inlocuit sensor de temperatura ,inlocuit electrovalva apa la DGASPC SECTOR 1 / CSS. ODAI
