
SERVICII DE REPARATIE CHILLER INTERKLIMA MPCA-18

I.D.: 50419456

Data publicarii	07.10.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 3.651,00 RON - 3.651,00 RON

Descriere: SERVICII DE REPARATIE CHILLER INTERKLIMA MPCA-18 : 1 ELECTROD SUDURA AG BC 2X 45.00 = 90.00 2 FREON R407C KG 18 X110.00 = 1980.00 3 SUBSTANTA IDENTIFICARE NEETANSEITATI BC 2X 48.00= 96.00 4 AZOT BC 1X 285.00 =285.00 5 MANOPERA H 10 X120.00= 1200.00
