
Reparatie B 49 TWR

I.D.: 97659196

Data
publicarii 20.05.24

Coduri CPV

50112200-5

Pretul
estimativ: 545,75 RON - 545,75 RON

Descriere: Materiale -Ulei cutie -Bec W5W 12V 5W Manopera -Conducta de admisie servo directie
inlocuit -Ulei servo - complectare -Bec lumini de frana suplimentare inlocuire -Conducta servo
reparat
