
Servicii de reparatie Water Chiller

I.D.: 93754879

Data publicarii	21.02.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 2.040,00 RON - 2.040,00 RON

Descriere: Reparatie chiller, include: valva solenoida, placa de baza, intrerupator, capacitor 6.5UF pentru LW500, plus manopera inlocuire componente Servicii de reparatie Water Chiller H50-500, constand in: SZL-PTF018/145 Valva solenoida+ inlocuire valva solenoida 1 buc x 1,174.00 = 1,174.00 SDL-DYB014 Placa de baza + inlocuire placa de baza 1 buc x 670.00 = 670.00 SDL-DYG002 Intrerupator + inlocuire intrerupator 1 buc x 101.00 = 101.00 SDL-DR002 Capacitor of LW500 6.5UF/ Capacitor pentru LW500 6.5UF+inlocuire 1 buc x 95.00 = 95.00 Inklusiv Manopera service
