
reparatie pompa

I.D.: 90846077

Data publicarii	15.12.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 4.300,00 RON - 4.300,00 RON

Descriere: Conditii refuzate: demontat montat, rebobinat stator, inlocuit 2 buc.etansari mecanice inlocuit rulmenti SKF, ulei SHELL ONDINA, inlocuit cablu de alimentare
