

Serviciu mentenanta, reparatie Image Scanner Assembly, inlocuire fuser, inlocuire role tava 2

I.D.: 105570598

Data publicarii	12.11.24	Coduri CPV	50323100-6 50000000-5
-----------------	----------	------------	-----------------------

Pretul estimativ:	559,91 RON - 559,91 RON
-------------------	-------------------------

Descriere:	Serviciu mentenanta, reparatie Image Scanner Assembly, inlocuire fuser, inlocuire role tava 2 HP M426FDN
------------	--
