
Reparati pompe

I.D.: 73924722

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 07.10.22 | Coduri CPV | 50511000-0 |
|-----------------|----------|------------|------------|

Pretul estimativ: 5.130,00 RON - 5.130,00 RON

Descriere: Aprov.-BECLEAN- Nr.neces.737/05.10.2022-Reparatia consta in rebobinat, inlcuire rulmenti, inlcuire etansari tip presutupa , ulei.-Nr.neces.17048/11.08.2022 Reparatia consta in rebobinare si inlocuire etansari.-Nr.neces.17719/22.08.2022Reaparatia consta in rebobinare si schimbare etansari.-Nr.neces.11389/07.06.2022Reaparatia consta in rebobinare si schimbare etansari.
