
Servicii de reparare si intretinere (Rev.2)

I.D.: 39771791

Data publicarii	17.05.18	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ:	1.197,48 RON - 1.197,48 RON
-------------------	-----------------------------

Descriere:	inlocuit bobina inductie senzot pozitie arbore cotit , pompa benzina . garnitura admisie bujii , fise bujii. freon
------------	--
