
LUCRARI DE INTRETINERE VW T6

I.D.: 50400586

Data publicarii	05.10.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.813,96 RON - 1.813,96 RON

Descriere: Manopera (Inspectie service conform listei fabricantului, inlocuire lichid frana, inlocuire ulei cuplaj HALDEX, inlocuire placute de frana fata si spate) = 627,25 lei Materiale (lichid frana, ulei cuplaj HALDEX, placute de frana fata si spate) = 1186,71 lei
