
Reparatie accidentala sterilizator cu abur

I.D.: 72176500

Data publicarii	12.08.22	Coduri CPV	50800000-3 50421000-2
-----------------	----------	------------	-----------------------

Pretul estimativ: 7.010,00 RON - 7.010,00 RON

Descriere: iesele necesare reparatiei monitoarelor de functii vitale PVM-4753, conform FT de constatare 4630/ 12.07.2022: 1. Ecran tactil capacitiv RPA-6141900846 2650,00 2 buc. 5.300,00 2. 2 ore constatare tehnica ecrane tactile defecte 4 ore manopera inlocuire ecrane tactile si testare 285,00 6 ore 1.710,00 Total: 7.010 RON
