

---

## Reparatie auto Mercedes Sprinter Trituro

I.D.: 77892708

---

Data publicarii	26.01.23	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 3.033,61 RON - 3.033,61 RON

---

Descriere: Reparatie auto IS-10- GYE COMPRESOR AER BILSTEIN - 1bc X 2042.02 = 2042.02 RON SUPORT CUTIE VITEZE - 1bc X 151.26 = 151.26 RON BUTON COMANDA COMPRESOR - 1bc X 50.42 = 50.42 RON RELEU CURENT ALIMENTARE - 1bc X 33.61 = 33.61 RON DEMONTAT/ MONTAT SUPORT CUTIE VITEZE - 1h X 168.07 = 168.07 RON VERIFICARE/ CONSTATARE AX CARDANIC - 1h X 168.07 = 168.07 RON INSTALARE SISTEM AUXILIAR INCARCARE AER SUSPENSIE PNEUMATICA - 2.5h X 168.07 = 420.17 RON

---