

---

## **constatare tehnica si remediere defectiune Criomicrotom Leica**

I.D.: 43501992

---

Data publicarii	08.07.19	Coduri CPV	50800000-3 50000000-5
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 6.027,00 RON - 6.027,00 RON

---

Descriere: Constatate tehnica si remediere defectiune criomicrotom ce consta in: verificare instalatie electrica, verificare senzori lampa pornire lampa UV, inlocuire lampa UV. Pret 1086 RON fara TVA 2 Lampa UV. Pret 4941 RON fara TVA

---