
Servicii de reparare si de intretinere a echipamentului de stingere a incendiilor

I.D.: 105932258

Data publicarii	18.11.24	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ: 2.149,00 RON - 2.149,00 RON

Descriere: 1 Verificare hidranti interiori Buc 5*70.00lei=350.00lei 2 Verificare stingator tip P6 Buc 28*25.00lei= 700.00lei 3 Verificare stingator tip G5 Buc 4*25.00lei=100.00lei 4 Verificare stingator tip P2 Buc 1*20.00lei=20.00lei 5 Verificare stingator tip P1 Buc 2*20.00lei=40.00 lei 6 Presurizat stingator tip P6 Buc 8*25.00lei=200.00lei 7 Incarcat stingator tip P6 Buc 1*70.00 lei=70.00lei 8 Incarcat stingator tip G5 Buc 1*60.00lei=60.00lei 9 Presurizare stingator tip P2 Buc 1*19.00lei=19.00lei 10 Stingator tip P2 cu suport Buc 1*100.00lei= 100.00lei 11 Stingator tip G2 Buc 1*190.00lei=190.00lei 12 Stingator tip P6 Buc 2*150.00lei=300.00lei
