
Servicii de reparare uscator de rufe ind. Ipso

I.D.: 90815099

Data publicarii	13.12.23	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.100,00 RON - 1.100,00 RON

Descriere: Reparatie uscator industrial de rufe IPSO : inlocuit element rezistenta termica, inlocuit senzor temperatura la DGASPC SECTOR 1/ CSS. Straulesti
