
REPARATII POMPA SUMERSIBILE

I.D.: 62280015

Data publicarii	21.10.21	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 1.716,00 RON - 1.716,00 RON

Descriere: REPARATII POMPA SUMERSIBILA 1.1 KW:rebobinat ; inlocuire rulmenti ; lucrari mecanice conexe ; REPARATII MIXER FLYGT 0670076:inlocuire rulmenti ; lucrari mecanice conexe ; REPARATII MIXER FLYGT 0670073: rebobinat
