
Reparatii mecanice:B107SKI

I.D.: 85546265

Data publicarii	04.08.23	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ:	897,48 RON - 897,48 RON
-------------------	-------------------------

Descriere: Reparatii mecanica:inlocuit senzor temperatura gaze evacuare, teava esapament primara,colier esapament, garnitura esapament
