
Servicii de reparare VW TRANSPORTER

I.D.: 40138804

Data publicarii	18.12.18	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 5.987,46 RON - 5.987,46 RON

Descriere: Servicii de reparare VW TRANSPORTER ce includ: inlocuire disc ambreiaj si placa presiune,surub placa presiune,rulment placa presiune,surub rulment presiune,volanta,surub,garnitura catalizator,element prindere catalizator,garnitura, clama dubla
