
Reparatii BN17PLI

I.D.: 43295861

Data publicarii	27.02.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	794,00 RON - 794,00 RON
----------------------	-------------------------

Descriere:	testare diagnoza dem/montat carcasa filtru aer dem/montat tubulatura aer inlocuit furtun
------------	--
