
Servicii de reparatie bidistilator Fistreem

I.D.: 56570156

Data publicarii	29.04.21	Coduri CPV	50400000-9 50421000-2
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.250,00 RON - 1.250,00 RON

Descriere: Reparatie prin inlocuirea furtunurilor siliconice, tuburi de apa si cuple rapide la Bidistilatorul Sanyo Gallenkamp Cyclon Fistreem de la Biologie Celulara si Moleculara
