

pachet materiale reparatii curente

I.D.: 62503997

Data publicarii 29.10.21 Coduri CPV 44411000-4

Pretul estimativ: 3.377,75 RON - 3.377,75 RON

Descriere: profil U 80=2x260.5050; teava neagra 15x15x1.5=1x28.5714; rentagrund 0.75l=1x16.3866; ciment romcim = 10x20.1680; lopata triton+coada= 1x43.6975; saci rafie=5x1.26; racord flexibil=1x6.7227; surub cap torbant 8x100=25x1.2604; piulita 8=25x0.084; saiba plata 8= 25x0.1680; pensula 36mm=1x3.3613; rezerva trafalet=3x1.26; disc lamelar=4x8.4025; vopsea ecolux=2x29.41; vopsea pitura 0.6l=1x9.2437; burghiu metal 10=1x28.5714; burghiu metal 8=1x18.4874; cherestea=0.200x1512.60; surub lemn 3.5x20=300x0.042; butuc 80/90m=1x17.6471; rezervor wc beta=1x96.6387; surub cap torbant 6x50=60x0.4202; piulita 6=60x0.042; vinclu imbinare=35x1.6806; surub lemn 3x20=100x0.042; buton mobilier=50x3.3614; vopsea ecolux=6x29.4117; vopsea pitura 0.6l=4x9.2425; smirghel=4x2.52; lampa ovala 60w=5x17.648; wd-40 400ml=1x27.7311; cot ppr 20/90*=40x0.5043; robinet flotor=1x29.4118; cot bz 1/2=6x5.8817; racord flexibil=38x6.7226; niplu bz1/2=10x2.9410; teu bz 1/2=6x7.5633; supapa aerisire1/2=3x20.1667; teu ppr20x1/2=3x5.0433; cot ppr 20=30x0.5043; teava ppr 20=4x19.3275; surub boiler=6x5.0417; intinzator m6=5x2.10; brida cablu=10x0.588; cablu metalic=20x2.1010; surub lemn4x20=350x0.042; cuier satin=9x6.7222; cuier prosop=8x2.5213; rezervor beta wc= 1x96.6387; carlig zincat=1x6.7227; cablu metalic=20x2.1010; brida cablu=8x0.5888; morsete mb40=1x6.7227; morseta 6mm=1x6.7227=surub 4x20=50x0.042; vopsea pitura=5x9.244; intinzator=4x2.94; carlig=3x8.4033; mosor cu fir=1x34.4538; cot wc=1x25.2101 burghiu 10x210=1x11.7647; burghiu be