
Service hidranti interiori si stingatoare

I.D.: 60097687

Data publicarii	16.08.21	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ: 5.274,98 RON - 5.274,98 RON

Descriere: Service hidranti interiori: 47 buc x 35 lei Verificat stingator tip P1: 6 buc x 15.58 lei Verificat stingator tip G2: 16 buc x 18.5 lei Verificat stingator tip P6: 103 buc x 18.5 lei Robinet hidrant: 6 buc x 118 lei Manopera inlocuire robinet: 6 buc x 80 lei Mufa 2": 5 buc x 15 lei Rama sticla: 2 buc x 30 lei Plan de evacuare A3: 3 buc x 4 lei
