

---

## **Reparatie motoreductor Bauer, tip BG06- 31/D06LA8/SP**

I.D.: 42207110

---

Data publicarii	13.03.19	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 939,25 RON - 939,25 RON

---

Descriere: - Demontat motoreductor in parti componente, curatat piese demontate; - Efectuat masuratori electrice si dimensionale; Reparatie: - Inlocuit rulmenti si simering reductor; - Reconditionat arbore de iesire reductor in zona cotei de simering; - Inlocuit ulei reductor; - Inlocuit rulmenti si simeringuri motor; - Asamblat motoreductor;

---