
Reparare Antena de cap (16E Head Neck Array Coil) = aug21

I.D.: 60105137

Data publicarii	18.08.21	Coduri CPV	98300000-6
-----------------	----------	------------	------------

Pretul estimativ: 35.500,00 RON - 35.500,00 RON

Descriere: Reparare Antena de cap (16E Head Neck Array Coil) de la echipamentul RMN Signa Explorer 1.5T Conditii comerciale: - Reparatia beneficiaza de o garantie de 60 de zile; - Termenul de returnare a antenei reparate la Beneficiar este de aproximativ 14 zile, in conditii normale de transport international.; FE 1552/09.08.2021
