
TM 2334/AB REPARATIE CAMERA SONY

I.D.: 64030919

Data publicarii	07.12.21	Coduri CPV	50341000-7
-----------------	----------	------------	------------

Pretul estimativ:	750,00 RON - 750,00 RON
----------------------	-------------------------

Descriere:	Reparatie camera profesionala tip SONY PXW-X160, prin inlocuire componente viewfinder.
------------	--
