
Reparatie Histeroscop Campo Trophyscope

I.D.: 50421034

Data publicarii	06.10.20	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 9.000,00 RON - 9.000,00 RON

Descriere: Reparatie Campo Trophyscope (inlocuire in regim de schimb) conform deviz nr. VI2946/01.10.2020 Reparatie prin inlocuire Campo Trophyscope DEFECTIUNI CONSTATATE lentila cilindrica sparta, varf histeroscop deteriorat mecanic, teaca histeroscop indoita OPERATIUNI EXECUTATE inlocuire histeroscop
