
Reparatie Histeroscop Campo Trophyscope

I.D.: 50421034

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 06.10.20 | Coduri CPV | 50421000-2 |
|-----------------|----------|------------|------------|

Pretul estimativ: 9.000,00 RON - 9.000,00 RON

Descriere: Reparatie Campo Trophyscope (inlocuire in regim de schimb) conform deviz nr. VI2946/01.10.2020 Reparatie prin inlocuire Campo Trophyscope DEFECTIUNI CONSTATATE lentila cilindrica sparta, varf histeroscop deteriorat mecanic, teaca histeroscop indoita OPERATIUNI EXECUTATE inlocuire histeroscop
