
Serviciu reparatie motocoasa HITACHI CG 47 EYT

I.D.: 38273827

Data publicarii	06.09.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Termenul limita pentru depunere:	09.09.19	Pretul estimativ:	200,00 RON - 290,00 RON
----------------------------------	----------	-------------------	-------------------------

Descriere: Serviciu reparatie motocoasa HITACHI CG 47 EYT astfel: 1. reparatie motocoasa = 1 buc; Constatari tehnice: a) Carburator infundat; b) Cap reductor inferior defect c) Autocut defect. Necesari materiale / servicii: a) inlocuit cap reductor - 1 buc; b) inlocuit autocut = 1 buc.
