

---

## Efectuare reparatie Mercedes si Fiat Doblo

I.D.: 30585153

---

Data publicarii	07.09.18	Coduri CPV	50100000-6
-----------------	----------	------------	------------

---

Termenul limita pentru depunere:	11.09.18	Pretul estimativ:	1.000,00 RON
----------------------------------	----------	-------------------	--------------

---

Descriere: 1. Efectuare reparatie Mercedes benz axor VL12ACV, serie : WDB9505011L357357, 2008 - inlocuire radiator racire apa - producator OE Hella + anitgel Hepu compatibil + filtru regulator de aer - lubrifiant - condens 1/4" - 10 bar temp. max.60 grade - model yato - 2385 + manopera 2. Efectuare reparatie Fiat Doblo VL10ACV seria : ZFA22300005610740, 2008 - inlocuire bujii incandescente - 4 buc ( producator NGK/Bosch ) + manopera

---