
Servicii reparatii aparate aer conditionat

I.D.: 48200650

Data publicarii	17.07.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 612,00 RON - 612,00 RON

Descriere: Lucrari de reparatii aparat aer conditionat, constand in inlocuire senzor unitate externa si incarcat cu freon R410 A aparate aer conditionat capacitate nominala - maxim 700 gr, inlocuit condensator 3 Mf/250 V. Include manopera.
