

---

## Reparatie masina de spalat Beko 7 kg

I.D.: 49256151

---

Data publicarii	27.08.20	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 350,00 RON - 350,00 RON

---

Descriere: - Constatat defect: 50.00 Ron - Inlocuit subansamble - inchizator lacat: 80.00 Ron - Inlocuit carbuni: 90.00 Ron - Verificare/ probe functionare: 40.00 Ron - Inchizator lacat Arctic: 50.00 Ron - Carbuni: 2 x 20.00= 40.00 Ron

---