
Servicii de reparatii masina de spalat rufe LG

I.D.: 93411149

Data
publicarii 13.02.24

Coduri CPV

50800000-3

Pretul
estimativ: 1.198,87 RON - 1.198,87 RON

Descriere: Servicii de reparatii masina de spalat rufe LG - inlocuire inchizator complet 1 buc, garnitura hublou - 1 buc cf referat 5455/02.02.2024
