



reparat pompa injectie tip LUCAS V8 PERKINS

I.D.: 93084882

Data
publicarii

06.02.24

Coduri CPV

50110000-9

Pretul
estimativ:

2.000,00 RON - 2.000,00 RON

Descriere: reparat pompa injectie tip LUCAS V8 PERKINS(reparat regulator acceleratie si inlocuit
simeringuri etansare ax antrenare) conform comanda reparatii
