

Reparatie Imprimanta Lexmark MS510

I.D.: 42700781

Data publicarii	07.05.19	Coduri CPV	50312000-5 50313200-4
-----------------	----------	------------	-----------------------

Pretul estimativ: 250,00 RON - 250,00 RON

Descriere: Reparatie cuptor; inlocuire fixing film; inlocuire role tractare hartie din tava1. Testare si verificare imprimanta (RAR ARGES NR 905 / 15.04.2019)
