
Servicii de reparare si intretinere auto Hyundai Tucson NT 28 API

I.D.: 55821529

Data publicarii	06.04.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 247,26 RON - 247,26 RON

Descriere: Servicii de reparare si intretinere auto Hyundai Tucson NT 28 API:senzor impulsuri arbore cotit = 151.26 lei manopera inlocuit senzor impulsuri arbore cotit = 3h x 32.00 lei(ora) = 96.00 lei CF.dEVIZ NR.3241/31.03.2021
