

---

## Servicii de reparatie ecograf HD5 prin inlocuire de sonda C8-4v

I.D.: 60187064

---

Data publicarii	20.08.21	Coduri CPV	50421000-2
-----------------	----------	------------	------------

---

Pretul estimativ:	16.831,88 RON - 16.831,88 RON
-------------------	-------------------------------

---

Descriere: Acceptul nostru tine loc de nota de comanda ferma. Va rugam sa efectuati livrarea.  
Conform catalog SICAP. Referat OG nr ...../ 17.8.2021

---