

---

## Reparatie sistem climatizare tip CHILLER sala sport

I.D.: 70952258

---

Data publicarii	05.07.22	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.860,11 RON - 1.860,11 RON
-------------------	-----------------------------

---

Descriere:	remediere traseu frigorific prin brazare, inlocuire fittinguri Cu, curatare cu azot.
------------	--

---