

---

## Servicii de reparatie auto Ford Ecosport

I.D.: 90824900

---

Data publicarii	15.12.23	Coduri CPV	50110000-9 50112000-3
-----------------	----------	------------	-----------------------

---

Pretul estimativ:	7.965,33 RON - 7.965,33 RON
-------------------	-----------------------------

---

Descriere:	Inlocuit pompa ulei si curea pompa ulei Inlocuit kit distributie si pompa apa Pretul include piese si manopera
------------	--

---