

Servicii mecanice - inlocuire racitor EGR , antigel , pentru VW Sharan HD 75 SSP ,

I.D.: 63799291

Data publicarii 02.12.21 Coduri CPV 50110000-9

Pretul estimativ: 3.916,30 RON - 3.916,30 RON

Descriere: Servicii mecanice - inlocuire racitor EGR , antigel , pentru VW Sharan HD 75 SSP , conform deviz atasat. Efectuat receptie directa 0.00 17/11/2021; Functie apelabila ; Filtru particule demo si montat ; Radiator gaze recirculate demo si montat . Comandat Loc.magazie RACITOR EGR 1.00 1,935.00 1,935.00 30 livrat N D V 03L131547N Garnitura 4.00 32.45 32.45 30 livrat N D PE9-2/07/2 V 04L131547S Garnitura 1.00 61.80 61.80 30 livrat N D PE8/2/04/5 V 03P131521E Teava de legatura 1.00 247.00 247.00 30 livrat N D V 03P131521A Teava de legatura 1.00 247.00 247.00 30 livrat N D V N 91032702 surub, cap semirotond cu 6.00 4.40 4.40 30 livrat N D V N 90894601 PIULITA M10 2.00 6.60 6.60 30 livrat N D PE8/2/04/6 V 1K0253115T GARNITURA DPF 1.00 25.25 25.25 30 livrat N D V 1K0253725 COLIER FILTRU PARTICULE 1.00 154.50 154.50 30 livrat N D V N 90991002 Surub cu cap cilindric si 6.00 9.10 9.10 30 livrat N D V WHT005437A SURUB PLANETARA EXT 1.00 22.95 22.95 30 livrat N V G 12E050A2 ANTIGEL G12 EVO 1L 5.00 39.65 39.65 30 livrat N D V N 10332002 PIULITA M10 6.00 6.05 6.05 30 livrat N D PD6/2/05/2 V 03L145757Q Garnitura 1.00 22.75 22.75 30 livrat N N I8-07/6 1 V WHT005635A Surub tabular 1.00 54.00