
Servicii de reparare si de intretinere a automobilelor (Rev.2)

I.D.: 42881786

Data publicarii	30.05.19	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.265,82 RON - 1.265,82 RON

Descriere: servicii de reparare si intretinere auto Hyundai Tucson NT-28-API set disc frana = 218.49 lei;placute frana = 167.23 lei;etrier spate = 345.38 lei manopera inlocuit discuri+placute+etrier = 5h x 32.00(ora) =160.00 lei ulei motor 5W-40 1l = 3 l x 27.14 lei = 81.42 lei completare ulei motor = 15min. x 32.00(ora) = 8.00 lei rulment roata spate = 264.71 lei manopera inlocuit rulment roata = 3h x 32.00(ora) = 96.00 lei discount 7% pt.piese/materiale = 75.41 lei
