
Reparatie MAI 38893 Dacia Duster

I.D.: 92450778

Data publicarii	25.01.24	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 1.333,82 RON - 1.333,82 RON

Descriere: Inlocuit releu bujii , inlocuit bujii incandescente , demontat /remontat anexe motor , tester auto . IDevizul contine piese , consumabile si manopera aferenta inlocuirii lor.
