
Service stingatoare si hidranti interiori

I.D.: 47147737

Data publicarii	11.06.20	Coduri CPV	50413200-5
-----------------	----------	------------	------------

Pretul estimativ:	520,00 RON - 520,00 RON
-------------------	-------------------------

Descriere:	Service stingatoare si hidranti interiori-Verificat stingator tip P6: 16 buc x 15 lei Verificare hidrant interior: 8 buc x 35 lei
------------	---
