
Reparatie partiala automatatoare Bucher CC5006

I.D.: 66817346

Data publicarii	28.02.22	Coduri CPV	50111000-6 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ: 4.139,31 RON - 4.139,31 RON

Descriere: Reparatia contine: Brake pressure switch - senzor presiune franare - 1 buc Conducta combustibil racire ECU - 1 buc Capac rulment alternator - 1 buc Rulment alternator - 1 buc Rulment alternator I - 1 buc Releu alternator - 1 buc Materiale consumabile - 1 set Diagnoza computerizata suprastructura D/M inlocuit alternator Reparat alternator D/M inlocuit conducta combustibil racire ECU D/M inlocuit senzor presiune franare
