



Manopera Schimbare Placa FLLBD AGILENT 1100

I.D.: 93417287

Data
publicarii

14.02.24

Coduri CPV

50410000-2

Pretul
estimativ:

2.800,00 RON - 2.800,00 RON

Descriere: SVS_GEN PRESTARI SERVICII GENERALE- diagnoza detector FLD, inlocuire component FLL Board , verificare functionalitate, reconfigurare detector in configuratie HPLC ,punere in functiune detector FLD
